

Q.No	Question Content	Question Image	Category	Sub Category	Marks	Options Randomization	Type	Difficulty	Correct	Option1	Option2	Option3	Option4
17	_____ mode switch position lets you move the machine axes manually.		Glossary IV	Glossary IV	2		Single Choice	Brilliant	MDI	Edit 	Auto	MDI	
18	The development of first NC machine tool project was awarded to		Glossary V	Glossary V	2		Single Choice	Brilliant	MIT	Improved strength of thecomponents	FALSE	MIT	
19	The running cost of CNC is higher than conventional machine..		Glossary V	Glossary V	2		Single Choice	Brilliant	FALSE	Improved strength of thecomponents	FALSE	MIT	
20 is not the advantage of CNC machines.		Glossary V	Glossary V	2		Single Choice	Smart	Improved strength of thecomponents	Improved strength of thecomponents	FALSE	MIT	